
STO134 LED Stainless Steel

we-ef



Description

IP66, Class I. Class II on request. IK07. Marine-grade, diecast aluminium alloy with polished stainless steel frame. 5CE superior corrosion protection including PCS hardware. Silicone rubber gasket. Polycarbonate main lens. Two cable entries.


Pre-installation blockout is recommended for mounting in concrete, available on request.


Weight	1.20 kg				
Light distribution	diffused distribution				
Light source	LED-5W / 250 mA - 2700 K				
CRI	80				
Power supply	EC				
LEDs	1				
Rated input power	5.6 W				
Rated lumens (lm)					
LED Lumen	75.4				
Total Lumen	75.4				
Та	25				
Nominal Lumen (lm)					
LED Lumen	720				
Total Lumen	720				
Тс	25				

190-9039

we-ef

STO134 LED Stainless Steel





Specifications Material description

Body	Marine-grade die-cast aluminium alloy			
Lens	Polycarbonate			
Colours	Stainless Steel			
Gasket	Silicone rubber gasket			
Fasteners	PCS Polymer Coated Stainless Steel Hardware			
Ingress protection	IP66			
Impact resistance	IK07			
Corrosion resistance	5CE			

Electrical description

Power supply	220-240V / 50-60 Hz
Driver / Ballast	Integral EC electronic converter
Power factor	> 0.9
Surge protection	1-2/2 kV

Additional information

Lifetime	Ta=25° L80B10 > 54000h
Energy efficiency class	C-D (Light source)

190-9039

STO134 LED Stainless Steel

Mounting Accessories

Installation blockout

		D1	D2	D3	H1	H2	H3	Weight (kg)
130 C1]	270	338		65	107		0.90
		11 H2						
	[01 D2						
145 -C1	22	270	280	338	65	75	107	0.90
	H1 	H2 H3	3					
	D1	D2 D3	1					

we-ef

190-9039

STO134 LED Stainless Steel

Control

DALI interface

Description	Part ID	Additional information	С
DALI interface	430-0013	DALI variant. The luminaire is equipped with a DT6 Dali driver (Dali 2.0).	90
		Dali 2.0 -Application controllers and Input devices defined -Single-masters and multi-masters allowed -Event priorities defined -Separate addressing & grouping from control gear	
		Note: Mixing Dali 1 and Dali 2.0 drivers can cause problems because the addressin and the command scope has changed!	ıg