

The luminaire is equipped with a DT6 Dali driver (Dali 2.0).

- Dali 2.0
- Application controllers and Input devices defined
  - Single-masters and multi-masters allowed
  - Event priorities defined
  - Separate addressing & grouping from control gear

Note: Mixing Dali 1 and Dali 2.0 drivers can cause problems because the addressing and the command scope has changed!

| Description                                                                                                           | Part ID  | Additional information                                                     | C  |
|-----------------------------------------------------------------------------------------------------------------------|----------|----------------------------------------------------------------------------|----|
| DALI interface                                                                                                        | 430-0013 | DALI variant. The luminaire is equipped with a DT6 Dali driver (Dali 2.0). | 90 |
| Dali 2.0                                                                                                              |          |                                                                            |    |
| -Application controllers and Input devices defined                                                                    |          |                                                                            |    |
| -Single-masters and multi-masters allowed                                                                             |          |                                                                            |    |
| -Event priorities defined                                                                                             |          |                                                                            |    |
| -Separate addressing & grouping from control gear                                                                     |          |                                                                            |    |
| Note: Mixing Dali 1 and Dali 2.0 drivers can cause problems because the addressing and the command scope has changed! |          |                                                                            |    |